

Firmware Release Notes

Araknis 310 Series Switches

Version 1.0.02



Release Details

Release Date	6/10/2016	
Firmware Version	1.0.02	
Product SKUs Affected	AN-310-SW-R-8	AN-310-SW-R-8-POE
	AN-310-SW-R-16	AN-310-SW-R-16-POE
	AN-310-SW-R-24	AN-310-SW-R-24-POE

Resolved Functional/Local Issues

- Fixed issue where Trace Route would produce a cyclic page error with a warning showing “Unspecified error(Ox1EA)”.
- Fixed issue where the user was unable to disable Bandwidth Control without disabling all QoS functionality in the switch.

Resolved Cloud Issues

- Fixed issue where link speed, duplex mode, or port naming could not be changed via OvrC.

Contacting Technical Support

Phone: (866) 838-5052

Email: support@araknisnetworks.com